



## Occupational Safety and Health Administration

Inspection Number	1. Photo ID No.	2. Date/Time	3. Citation Number	4. Item Number	5. Instance No.
1148200	8835, 8848	5/18/2016	1	1	1



Note: Arrow is pointing to the rear window of the dozer where the impact of the strap/shackle struck the seat and the dozer operator.



This photo is the 4' X 20 synthetic strap that broke free from the shackle attached to the bucket of the excavator.